

VIN: 5YFBURHE5GP434836

MECHANICAL EMISSIONS SERVICES LLC

910 High Land Ave National City, CA, 91950 Ph 619 939 5143
Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)





Cert number: CRM-00003

VIN: 5YFBURHE5GP434836	Year: 2016	License Plate: R3	Owner: MARIA GUADALUPE PEREZ BARRON
Mfg In: United States	Make: Toyota	Model: Corolla	Odometer: 132094 miles (212584.16 KM)

Monitoring Information and certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	CERT Number:	CRM-00003	Geolocation:	Latt: 32.693726. Long: -115.504535
Comprehensive Catalyst Monitor	PASS	O2 Sensor Monitor	PASS			EXPIRE: 2024-12-25	EET ITN:X20240923824540
Overall Test Result	PASS	Catalyst Monitoring:	PASS	Inspector Name:		Date:	2024-09-25



Certificate PDF:



Inspector signature:

Semarnat Authorization Letter No.
SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 software Version: 1602800772783
Help? Contact us at
support@mechanicalemissionservicesllc.com
To verify this Certificate please go to:
www.mechanicalemissionservicesllc.com