


# MECHANICAL EMISSIONS SERVICES LLC

910 High Land Ave National City, CA, 91950 Ph 619 939 5143  
 Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Cert number: CRM-00018



VIN: 3KPF24AD4KE028911



VIN: **3KPF24AD4KE028911**  
 Mfg In: **Mexico**





Year: **2019**  
 Make: **KIA**

License Plate: **R3**  
 Model: **Forte**

Owner: **ADOLFO PEÑA ESPINOZA**  
 Odometer: **141050 miles (226997.41 KM)**

### Monitoring Information and certificate

Misfire Monitor	<b>PASS</b>	Fuel System Monitor	<b>PASS</b>	CERT Number:	<b>CRM-00018</b>	Geolocation:	<b>Latt: 32.40400. Long: -115.29558</b>
Comprehensive Catalyst Monitor	<b>PASS</b>	O2 Sensor Monitor	<b>PASS</b>			<b>EXPIRE: 2024-12-26</b>	<b>EEl ITN: X20240923852348</b>
Overall Test Result	<b>PASS</b>	Catalyst Monitoring:	<b>PASS</b>	Inspector Name:	<b>ZAMANTHA TRUCIOS</b>	Date:	<b>2024-09-26</b>



Certificate PDF:



Inspector signature:

**ZAMANTHA TRUCIOS**

Semarnat Authorization Letter No. SRA.600/DPRA/DPMR/377/2022  
 CA BAR 97 GEN3 and/or Drew Technologies IMClean  
 ESP 10400-89 software Version: 1602800772783  
 Help? Contact us at support@mechanicalemissionservicesllc.com  
 To verify this Certificate please go to: [www.mechanicalemissionservicesllc.com](http://www.mechanicalemissionservicesllc.com)