

VIN: 19XFC2F78JE006316

# MECHANICAL EMISSIONS SERVICES LLC

910 High Land Ave National City, CA, 91950 Ph 619 939 5143  
Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CRM-00023

VIN: 19XFC2F78JE006316  
Mfg In: USA



Year: 2018  
Make: Honda

License Plate: R3  
Model: Civic

Owner: IMPORTACIONES RL SA CV  
Odometer: 54453 miles (87633.39 KM)

### Monitoring Information and certificate

Misfire Monitor	<b>PASS</b>	Fuel System Monitor	<b>PASS</b>	CERT Number:	<b>CRM-00023</b>	Geolocation:	<b>Latt: 32.40400. Long: -115.29558</b>
Comprehensive Catalyst Monitor	<b>PASS</b>	O2 Sensor Monitor	<b>PASS</b>			<b>EXPIRE: 2024-12-26</b>	<b>EEl ITN:X20240923890713</b>
Overall Test Result	<b>PASS</b>	Catalyst Monitoring:	<b>PASS</b>	Inspector Name:	ZAMANTHA TRUCIOS	Date:	<b>2024-09-26</b>



Certificate PDF:



Inspector signature:

*ZAMANTHA TRUCIOS*

Semarnat Authorization Letter No.  
SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean  
ESP 10400-89 software Version: 1602800772783  
Help? Contact us at  
support@mechanicalemissionservicesllc.com  
To verify this Certificate please go to:  
<https://n9.cl/reportlistmechanical>