



VIN: 5NPE34AF5JH628423

# MECHANICAL EMISSIONS SERVICES LLC



910 High Land Ave National City, CA, 91950 Ph 619 939 5143  
Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CRM-00025

VIN: <b>5NPE34AF5JH628423</b>	Year: <b>2018</b>	License Plate: <b>R3</b>	Owner: <b>MARIA GUADALUPE PEREZ BARRON</b>
Mfg In: <b>United States</b>	Make: <b>Hyundai</b>	Model: <b>Sonata</b>	Odometer: <b>114504 miles (184275.87 KM)</b>

Monitoring Information and certificate				CERT Number:	CRM-00025	Geolocation:	Latt: 32.40400. Long: -115.29558
Misfire Monitor	<b>PASS</b>	Fuel System Monitor	<b>PASS</b>			<b>EXPIRE: 2024-12-26</b>	EEl ITN: X20240923891137
Comprehensive Catalyst Monitor	<b>PASS</b>	O2 Sensor Monitor	<b>PASS</b>	Inspector Name:	ZAMANTHA TRUCIOS	Date:	2024-09-26
Overall Test Result	<b>PASS</b>	Catalyst Monitoring:	<b>PASS</b>				



Certificate PDF:



Inspector signature:

**ZAMANTHA TRUCIOS**

Semarnat Authorization Letter No.  
 SRA.600/DPRA/DPMR/377/2022  
 CA BAR 97 GEN3 and/or Drew Technologies IMClean  
 ESP 10400-89 software Version: 1602800772783  
 Help? Contact us at  
 support@mechanicalemissionservicesllc.com  
 To verify this Certificate please go to:  
<https://n9.cl/reportlistmechanical>