

VIN: 3VWE57BU1KM042397

MECHANICAL EMISSIONS SERVICES LLC



910 High Land Ave National City, CA, 91950 Ph 619 939 5143
Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CRM-00035

VIN: 3VWE57BU1KM042397	Year: 2019	License Plate: R3	Owner: MARIA GUADALUPE PEREZ BARRON
Mfg In: Mexico	Make: Volkswagen	Model: Jetta	Odometer: 1651841 miles (2658373.79 KM)

Monitoring Information and certificate							
Misfire Monitor	PASS	Fuel System Monitor	PASS	CERT Number:	CRM-00035	Geolocation:	Latt: 32.40400. Long: -115.29558
Comprehensive Catalyst Monitor	PASS	O2 Sensor Monitor	PASS			EXPIRE: 2024-12-27	EEl ITN: X20240918642453
Overall Test Result	PASS	Catalyst Monitoring:	PASS	Inspector Name:	ZAMANTHA TRUCIOS	Date:	2024-09-27



Certificate PDF:



Inspector signature:

ZAMANTHA TRUCIOS

Semarnat Authorization Letter No. SRA.600/DPRA/DPMR/377/2022
 CA BAR 97 GEN3 and/or Drew Technologies IMClean
 ESP 10400-89 software Version: 1602800772783
 Help? Contact us at
 support@mechanicalemissionservicesllc.com
 To verify this Certificate please go to:
<https://n9.cl/reportlistmechanical>