


# MECHANICAL EMISSIONS SERVICES LLC

910 High Land Ave National City, CA, 91950 Ph 619 939 5143  
 Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CRM-00037



VIN: 5YFBURHE1HP691333

VIN: **5YFBURHE1HP691333**  
 Mfg In: **Canada**


Year: **2017**  
 Make: **Toyota**

License Plate: **R3**  
 Model: **Corolla**

Owner: **ADOLFO PEÑA ESPINOZA**  
 Odometer: **52969 miles (85245.13 KM)**

### Monitoring Information and certificate

Misfire Monitor	<b>PASS</b>	Fuel System Monitor	<b>PASS</b>	CERT Number:	<b>CRM-00037</b>	Geolocation:	<b>Latt: 32.40400. Long: -115.29558</b>
Comprehensive Catalyst Monitor	<b>PASS</b>	O2 Sensor Monitor	<b>PASS</b>			<b>EXPIRE: 2024-12-30</b>	<b>EEl ITN: X20240925023428</b>
Overall Test Result	<b>PASS</b>	Catalyst Monitoring:	<b>PASS</b>	Inspector Name:	<b>ZAMANTHA TRUCIOS</b>	Date:	<b>2024-09-30</b>



Certificate PDF:



Inspector signature:

**ZAMANTHA TRUCIOS**

Semarnat Authorization Letter No.  
 SRA.600/DPRA/DPMR/377/2022  
 CA BAR 97 GEN3 and/or Drew Technologies IMClean  
 ESP 10400-89 software Version: 1602800772783  
 Help? Contact us at  
 support@mechanicalemissionservicesllc.com  
 To verify this Certificate please go to:  
<https://n9.cl/reportlistmechanical>