



VIN: 3CZRU5H53KM712389

# MECHANICAL EMISSIONS SERVICES LLC

910 High Land Ave National City, CA, 91950 Ph 619 939 5143  
Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CRM-00081

VIN: **3CZRU5H53KM712389**  
Mfg In: **United Kingdom**







Year: **2019**  
Make: **Honda**

License Plate: **R3**  
Model: **HR-V**

Owner: **ADOLFO PEÑA ESPINOZA**  
Odometer: **36922 miles (59420.05 KM)**

### Monitoring Information and certificate

Misfire Monitor	<b>PASS</b>	Fuel System Monitor	<b>PASS</b>	CERT Number:	<b>CRM-00081</b>	Geolocation:	<b>Latt: 32.40400. Long: -115.29558</b>
Comprehensive Catalyst Monitor	<b>PASS</b>	O2 Sensor Monitor	<b>PASS</b>			<b>EXPIRE: 2025-02-11</b>	<b>EET ITN:X20241107445937</b>
Overall Test Result	<b>PASS</b>	Catalyst Monitoring:	<b>PASS</b>	Inspector Name:	<b>ZAMANTHA TRUCIOS</b>	Date:	<b>2024-11-11</b>



Certificate PDF:



Inspector signature:

**ZAMANTHA TRUCIOS**

Semarnat Authorization Letter No. SRA.600/DPRA/DPMR/377/2022  
CA BAR 97 GEN3 and/or Drew Technologies IMClean ESP 10400-89 software Version: 1602800772783  
Help? Contact us at support@mechanicalemissionservicesllc.com  
To verify this Certificate please go to: <https://n9.cl/reportlistmechanical>