



VIN: 5YFBURHE2GP518130

# MECHANICAL EMISSIONS SERVICES LLC


910 High Land Ave National City, CA, 91950 Ph 619 939 5143  
Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CRM-00088

VIN: <b>5YFBURHE2GP518130</b>	Year: <b>2016</b>	License Plate: <b>R3</b>	Owner: <b>ADRIANA ANGELICA BENGUIAT JIMENEZ</b>
Mfg In: <b>Canada</b>	Make: <b>Toyota</b>	Model: <b>Corolla</b>	Odometer: <b>94633 miles (152296.67 KM)</b>

Monitoring Information and certificate							
Misfire Monitor	<b>PASS</b>	Fuel System Monitor	<b>PASS</b>	CERT Number:	<b>CRM-00088</b>	Geolocation:	<b>Latt: 32.4040. Long: -115.29558</b>
Comprehensive Catalyst Monitor	<b>PASS</b>	O2 Sensor Monitor	<b>PASS</b>			<b>EXPIRE: 2025-02-11</b>	<b>EEl ITN: X20241107452090</b>
Overall Test Result	<b>PASS</b>	Catalyst Monitoring:	<b>PASS</b>	Inspector Name:	<b>ZAMANTHA TRUCIOS</b>	Date:	<b>2024-11-11</b>



Certificate PDF:



Inspector signature:

**ZAMANTHA TRUCIOS**

Semarnat Authorization Letter No. SRA.600/DPRA/DPMR/377/2022  
 CA BAR 97 GEN3 and/or Drew Technologies IMClean  
 ESP 10400-89 software Version: 1602800772783  
 Help? Contact us at  
 support@mechanicalemissionservicesllc.com  
 To verify this Certificate please go to:  
<https://n9.cl/reportlistmechanical>