

MECHANICAL EMISSIONS SERVICES LLC

910 High Land Ave National City, CA, 91950 Ph 619 939 5143
 Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CRM-00091



VIN: 3MZBN1V38JM246258

VIN: **3MZBN1V38JM246258**
 Mfg In: **MEXICO**


Year: **2018**
 Make: **Mazda**

License Plate: **R3**
 Model: **MAZDA3**

Owner: **ADOLFO PEÑA ESPINOZA**
 Odometer: **45775 miles (73667.54 KM)**

Monitoring Information and certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	CERT Number:	CRM-00091	Geolocation:	Latt: 32.40400. Long: -115.29558
Comprehensive Catalyst Monitor	PASS	O2 Sensor Monitor	PASS			EXPIRE: 2025-02-11	EET ITN: X20241107450612
Overall Test Result	PASS	Catalyst Monitoring:	PASS	Inspector Name:	ZAMANTHA TRUCIOS	Date:	2024-11-11



Certificate PDF:



Inspector signature:

ZAMANTHA TRUCIOS

Semarnat Authorization Letter No. SRA.600/DPRA/DPMR/377/2022
 CA BAR 97 GEN3 and/or Drew Technologies IMClean
 ESP 10400-89 software Version: 1602800772783
 Help? Contact us at support@mechanicalemissionservicesllc.com
 To verify this Certificate please go to: <https://n9.cl/reportlistmechanical>