

VIN: 3MZBM1U75FM136069

MECHANICAL EMISSIONS SERVICES LLC




910 High Land Ave National City, CA, 91950 Ph 619 939 5143
Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CRM-00095

VIN: 3MZBM1U75FM136069	Year: 2015	License Plate: R3	Owner: MARIA GUADALUPE PEREZ BARRON
Mfg In: MEXICO	Make: Mazda	Model: MAZDA3	Odometer: 134584 miles (216591.41 KM)

Monitoring Information and certificate				CERT Number:	CRM-00095	Geolocation:	Latt: 32.4040. Long: -115.29558
Misfire Monitor	PASS	Fuel System Monitor	PASS			EXPIRE: 2025-02-12	EEl ITN: X20240929231434
Comprehensive Catalyst Monitor	PASS	O2 Sensor Monitor	PASS	Inspector Name:	ZAMANTHA TRUCIOS	Date:	2024-11-12
Overall Test Result	PASS	Catalyst Monitoring:	PASS				



Certificate PDF:



Inspector signature:

ZAMANTHA TRUCIOS

Semarnat Authorization Letter No. SRA.600/DPRA/DPMR/377/2022
 CA BAR 97 GEN3 and/or Drew Technologies IMClean ESP 10400-89 software Version: 1602800772783
 Help? Contact us at support@mechanicalemissionservicesllc.com
 To verify this Certificate please go to: <https://n9.cl/reportlistmechanical>