


# MECHANICAL EMISSIONS SERVICES LLC

910 High Land Ave National City, CA, 91950 Ph 619 939 5143  
 Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CRM-00112



VIN: 3VWG57BU1KM104356

VIN: **3VWG57BU1KM104356**  
 Mfg In: **Mexico**





Year: **2019**  
 Make: **Volkswagen**

License Plate: **R3**  
 Model: **Jetta**

Owner: **ADOLFO PEÑA ESPINOZA**  
 Odometer: **33024 miles (53146.84 KM)**

### Monitoring Information and certificate

|                                |             |                      |             |                 |                         |                           |   |
|--------------------------------|-------------|----------------------|-------------|-----------------|-------------------------|---------------------------|---|
| Misfire Monitor                | <b>PASS</b> | Fuel System Monitor  | <b>PASS</b> | CERT Number:    | <b>CRM-00112</b>        | Geolocation:              | <b>Latt: 32.40400. Long: -115.29558</b> |
| Comprehensive Catalyst Monitor | <b>PASS</b> | O2 Sensor Monitor    | <b>PASS</b> |                 |                         | <b>EXPIRE: 2025-02-12</b> | <b>EEl ITN:X20241106366629</b>          |
| Overall Test Result            | <b>PASS</b> | Catalyst Monitoring: | <b>PASS</b> | Inspector Name: | <b>ZAMANTHA TRUCIOS</b> | Date:                     | <b>2024-11-12</b>                       |



Certificate PDF:



Inspector signature:

**ZAMANTHA TRUCIOS**

Semarnat Authorization Letter No. SRA.600/DPRA/DPMR/377/2022  
 CA BAR 97 GEN3 and/or Drew Technologies IMClean ESP 10400-89 software Version: 1602800772783  
 Help? Contact us at support@mechanicalemissionservicesllc.com  
 To verify this Certificate please go to: <https://n9.cl/reportlistmechanical>