


MECHANICAL EMISSIONS SERVICES LLC

910 High Land Ave National City, CA, 91950 Ph 619 939 5143

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CMXT-00003



VIN: 7FARW2H5XJE075927

VIN: 7FARW2H5XJE075927
Mfg In: UNITED STATES



Year: 2018
Make: Honda

License Plate: R3
Model: CR-V

Owner: Maria Guadalupe Perez Barron
Odometer: 64433 miles (103694.6 KM)

Monitoring Information and certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	CERT Number:	CMXT-00003	Geolocation:	Latt: 32.40400. Long: -115.29558
Comprehensive Catalyst Monitor	PASS	O2 Sensor Monitor	PASS			EXPIRE: 2024-12-27	EEl ITN:X20240924967626
Overall Test Result	PASS	Catalyst Monitoring:	PASS	Inspector Name:	Oscar Morales	Date:	2024-09-27



Inspector signature:

Oscar Morales

Semarnat Authorization Letter No.
SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 software Version: 1602800772783
Help? Contact us at
support@mechanicalemissionservicesllc.com
To verify this Certificate please go to:
www.mechanicalemissionservicesllc.com