



VIN: 3MZBM1U77GM307762

MECHANICAL EMISSIONS SERVICES LLC

910 High Land Ave National City, CA, 91950 Ph 619 939 5143

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)



Cert number: CMXT-00028

VIN: **3MZBM1U77GM307762**
Mfg In: **MEXICO**

Year: **2016**
Make: **Mazda**

License Plate: **S2**
Model: **MAZDA3**

Owner: **LA LLAVE IMPORTS S.A DE C.V**
Odometer: **100470 miles (161690.39 KM)**

Monitoring Information and certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	CERT Number:	CMXT-00028	Geolocation:	Latt: 32.693726. Long: -115.504535
Comprehensive Catalyst Monitor	PASS	O2 Sensor Monitor	PASS			EXPIRE: 2025-02-12	EEl ITN:X20241106401188
Overall Test Result	PASS	Catalyst Monitoring:	PASS	Inspector Name:	Luis M	Date:	2024-11-12



